Approved For Releas CONFID ENTRAL 200457R005900170017-5 25X1 CINTRAL INTELLIGENCE AGENCY 2 Annex 2 to ______ 25X1

2 Two shed cranes, 5 tons each

In shipbuilding shop, one working since 1 January 1950 working

CONFIDENTIAL

Approved For Release 2003/08/11 : CIA-RDP82-00457R005900170017-5

CENTRAL INTELLIGENCE AGENCY

T

Annex to

25X1

Eschinery of the Shipbuilding Shed, Department 107 of the Neptun Shipyard, Rostock

TULLDE	er Kind of Eachine	Place and Date of Erection	Condition of Machine	es
ı	Drawing roller up to 10 rm	In front of building shed, August 1949	working	
3	Articulated boring machines, bore-hole diameters up to 21 mm	In shipbuilding shed, between August and December 1949	partially working, as motors are lack- ing	
ř.	Radial boring machines, maximum hole dismeter 22 mm	In shipbuilding shed, between August and December 1949	partially working as motors are lacking	3
6	Autogenous welding apparatus	In shipbuilding shed,	working	
10	Electrical welding apparatus	In shipbuilding shed, 1945/49, part of them outmoded	partially working, no cables	
1	Combined section and plate shears 100x100x10 10 mm 16 mm	In shipbuilding shed, new acquisition, September 1949	not yet working	
1	Combined punching machine and shears, 10 mm 26 mm	In shipbuilding shed, 1945 built in Glasgow in 1904	temporarily working only one cutter	
1	Combined punching machine converted for jossling and chasing	In shipbuilding shed, 1945, built, in Glasgow in 1904	working	
1	Combined shears and punching machine	In shipbuilding shed, 1945 built in Glasgow in 1904	working	
2	Countersinking benches	In the shipbuilding shop, date of erection prior to 1945	not working, out- moded	
1	Hydraulic water-press, 180 tons	In shipbuilding shed, October 1945	not working, erected in wrong place	
1	Plate-bending machine, 6 meters long, rolling up to 20 mm	In shipbuilding shed, October 1945	being repaired in December 1949	
1	Plate rolling machine up to 6 mm	In entrance hall to ship- building shop, year un- known, but before 1945	working	
1.	Plate press, 240 tons (hydraulic oil pressure)	In entrance hall to ship- building shop, September 1945	only partially work- ing due to shortage of replacement parts (leather)	
3.	Elephant press, hydraulic pressure, 340 tons	Entrance hall to ship- building shop, year un- known but before 1945	partially dismantled in 1945	
1	Hand buffer	shop, year unknown but	working	
1.	Combined machine buffer and punching machine	before 1945 In front of shipbuilding shop, year unknown but before 1945	working	

CONFIDENTIAL